













$d_0$	$\varnothing 8\text{mm}$

	$h_{nom}=70\text{mm}$	$t_{fix2}=0...10\text{mm}$
HUS3-C 8	$t_{fix1}$	$t_{fix1}+t_{fix2}$
8x75	5 mm	5...15 mm
8x85	15 mm	15...25 mm

$h_{nom}$	$h_1$
60	70
70	80

$h_{nom}$	$h_{1.nc}$	$h_{1.nc}$
60	94	70
70	104	80













$d_0$	$\varnothing 8\text{mm}$

	$h_{nom1}=50\text{mm}$	$h_{nom2}=60\text{mm}$	$h_{nom3}=70\text{mm}$
HUS3-C 8	$t_{fix1}$	$t_{fix2}$	$t_{fix3}$
8x65	15 mm	-	-
8x75	25 mm	15 mm	-
8x85	35 mm	25 mm	15 mm

$h_{nom}$	$h_1$
50	60
60	70
70	80








$h_{nom}$	$h_{1.nc}$	$h_{1.nc}$
50	84	60
60	94	70
70	104	80











$d_0$	Ø 8mm	Ø 6mm

$h_{nom2}=60mm$	
HUS3-C 8	$t_{fix2}$
8x65	-
8x75	15 mm
8x85	25 mm



$d_0$	Ø 8mm

min. $t_{fix}=5mm$	
HUS3-C 8	$t_{fix}$
8x65	5 mm
8x75	5 mm
8x85	15 mm



	SIW 22-A 1/2" (01)	SIW 6AT-A22 1/2" (01)	SIW 22T-A 1/2" (01)	SIW 22T-A 3/4" (01)	SIW 9-A22 3/4" (01)
HUS3-C 8	✓	✓	✓	✓	✗